

AD-A069 614

NEW JERSEY STATE DEPT OF ENVIRONMENTAL PROTECTION TRENTON F/G 13/2
NATIONAL DAM SAFETY PROGRAM. BEAVER DAM (NJ00077), DELAWARE RIV--ETC(U)
APR 79 F K JOLLS


DACW61-78-C-0124

NL

UNCLASSIFIED

1 OF
AD
A069614





LEVEL

WA069614

DELAWARE RIVER BASIN
BUCKSHUTEM CREEK
CUMBERLAND COUNTY
NEW JERSEY

(P)

BEAVER DAM
NJ 00077

DDC
RECEIVED
JUN 11 1979
MILITARY

PHASE 1 INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM



Approved for public release;
distribution unlimited

DDC FILE COPY

DEPARTMENT OF THE ARMY

Philadelphia District
Corps of Engineers
Philadelphia, Pennsylvania

April, 1979

79-00001-071

DISCLAIMER NOTICE

THIS DOCUMENT IS BEST QUALITY
PRACTICABLE. THE COPY FURNISHED
TO DDC CONTAINED A SIGNIFICANT
NUMBER OF PAGES WHICH DO NOT
REPRODUCE LEGIBLY.

THIS IS THE BEST
COPY AVAILABLE.

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER NJ00077	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Phase I Inspection Report National Dam Safety Program Beaver Dam Cumberland County, N.J.		5. TYPE OF REPORT & PERIOD COVERED ⑨ FINAL rept.
7. AUTHOR(s) ⑩ F. Keith Jolls PE		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS Louis Berger & Assoc. ✓ 100 Halstead St. East Orange, N.J. 07019		8. CONTRACT OR GRANT NUMBER(s) ⑪ DACW61-78-C-0124
11. CONTROLLING OFFICE NAME AND ADDRESS U.S. Army Engineer District, Philadelphia Custom House, 2d & Chestnut Streets Philadelphia, Pennsylvania 19106		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) ⑫ 67 p.		12. REPORT DATE ⑪ April, 1979
		13. NUMBER OF PAGES 62
		15. SECURITY CLASS. (of this report) Unclassified
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) Approved for public release; distribution unlimited.		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20; if different from Report) ⑬ National Dam Safety Program, Beaver Dam (NJ00077), Delaware River Basin, Buckshutem Creek, Cumberland County, New Jersey. Phase I Inspection Report.		
18. SUPPLEMENTARY NOTES Copies are obtainable from National Technical Information Service, Springfield, Virginia, 22151.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dams Visual Inspection Spillways National Dam Inspection Act Report Structural Analysis Beaver Dam, N.J. Safety		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report cites results of a technical investigation as to the dam's ade- quacy. The inspection and evaluation of the dam is as prescribed by the National Dam Inspection Act, Public Law 92-367. The technical investigation includes visual inspection, review of available design and construction records, and preliminary structural and hydraulic and hydrologic calculations, as applicable. An assessment of the dam's general condition is included in the report. 470 894		

NOTICE

**THIS DOCUMENT HAS BEEN REPRODUCED
FROM THE BEST COPY FURNISHED US BY
THE SPONSORING AGENCY. ALTHOUGH IT
IS RECOGNIZED THAT CERTAIN PORTIONS
ARE ILLEGIBLE, IT IS BEING RELEASED
IN THE INTEREST OF MAKING AVAILABLE
AS MUCH INFORMATION AS POSSIBLE.**



IN REPLY REFER TO

NAPEN-D

DEPARTMENT OF THE ARMY
PHILADELPHIA DISTRICT, CORPS OF ENGINEERS
CUSTOM HOUSE - 2 D & CHESTNUT STREETS
PHILADELPHIA, PENNSYLVANIA 19106



Honorable Brendan T. Byrne
Governor of New Jersey
Trenton, NJ 08621

25 MAY 1979

Dear Governor Byrne:

Inclosed is the Phase I Inspection Report for Beaver Dam in Cumberland County, New Jersey which has been prepared under authorization of the Dam Inspection Act, Public Law 92-367. A brief assessment of the dam's condition is given in the front of the report.

Based on visual inspection, available records, calculations and past operational performance, Beaver Dam, initially listed as a high hazard potential structure but reduced to a significant hazard potential structure as a result of this inspection, is judged to be in fair overall condition. However, the dam's spillway is considered inadequate since 30 percent of the Spillway Design Flood-SDF-would overtop the dam. (The SDF, in this instance, is one half of the Probable Maximum Flood.) To insure adequacy of the structure, the following actions, as a minimum, are recommended:

a. The spillway's adequacy should be determined by a qualified professional consultant engaged by the owner using more sophisticated methods, procedures, and studies within six months from the date of approval of this report. Any remedial measures necessary to insure the adequacy of the spillway and to prevent overtopping should be initiated within calendar year 1980.

b. Within one year from the date of approval of this report, the following actions should be taken:

- (1) Replace the deteriorated timber in the spillway.
- (2) Remove trees along the upstream crest of the dam and rebuild

NAPEN-D

Honorable Brendan T. Byrne

the crest shoulders.

(3) Remove trash in the spillway and downstream embankments.

(4) The randomly dumped concrete building plank should be broken up into smaller segments and seated more uniformly into the backslopes. A gravel bedding layer should be placed under the concrete pieces.

c. A checklist of periodic maintenance inspections should be developed so records of conditions and repairs can be maintained.

A copy of the report is being furnished to Mr. Dirk C. Hofman, New Jersey Department of Environmental Protection, the designated State Office contact for this program. Within five days of the date of this letter, a copy will also be sent to Congressman William J. Hughes of the Second District. Under the provision of the Freedom of Information Act, the inspection report will be subject to release by this office, upon request, five days after the date of this letter.

Additional copies of this report may be obtained from the National Technical Information Services (NTIS), Springfield, Virginia 22161 at a reasonable cost. Please allow four to six weeks from the date of this letter for NTIS to have copies of the report available.


Accession For	
NTIS GRA&I	
DDC TAB	
Unannounced	
Justification	
By	
Distribution/	
Availability Codes	
Dist	Avail and/or special
A	23

NAPEN-D

Honorable Brendan T. Byrne

An important aspect of the Dam Safety Program will be the implementation of the recommendations made as a result of the inspection. We accordingly request that we be advised of proposed actions taken by the State to implement our recommendations.

Sincerely,



JAMES G. TON
Colonel, Corps of Engineers
District Engineer

1 Incl
As stated

Copies furnished:

Dirk C. Hofman, P.E., Deputy Director
Division of Water Resources
N. J. Dept. of Environmental Protection
P. O. Box CN029
Trenton, NJ 08625

John O'Dowd, Acting Chief
Bureau of Flood Plain Management
Division of Water Resources
N. J. Dept. of Environmental Protection
P. O. Box CN029
Trenton, NJ 08625

BEAVER DAM (NJ00077)

CORPS OF ENGINEERS ASSESSMENT OF GENERAL CONDITIONS

This dam was inspected on 10 January 1979 by Louis Berger and Associates, Inc. under contract to the State of New Jersey. The State, under agreement with the U. S. Army Engineer District, Philadelphia, had this inspection performed in accordance with the National Dam Inspection Act, Public Law 92-367.

Beaver Dam, initially listed as a high hazard potential structure but reduced to a significant hazard potential structure as a result of this inspection, is judged to be in fair overall condition. However, the dam's spillway is considered inadequate since 30 percent of the Spillway Design Flood-SDF-would overtop the dam. (The SDF, in this instance, is one half of the Probable Maximum Flood.) To insure adequacy of the structure, the following actions, as a minimum, are recommended:

a. The spillway's adequacy should be determined by a qualified professional consultant engaged by the owner using more sophisticated methods, procedures, and studies within six months from the date of approval of this report. Any remedial measures necessary to insure the adequacy of the spillway and to prevent overtopping should be initiated within calendar year 1980.

b. Within one year from the date of approval of this report, the following actions should be taken:

- (1) Replace the deteriorated timber in the spillway.
- (2) Remove trees along the upstream crest of the dam and rebuild the crest shoulders.
- (3) Remove trash in the spillway and downstream embankments.
- (4) The randomly dumped concrete building plank should be broken up into smaller segments and seated more uniformly into the backslopes. A gravel bedding layer should be placed under the concrete pieces.

c. A checklist of periodic maintenance inspections should be developed so records of conditions and repairs can be maintained.

APPROVED: _____

JAMES G. TON
Colonel, Corps of Engineers
District Engineer

DATE: _____

20 May 1979

PHASE I REPORT
NATIONAL DAM INSPECTION PROGRAM


Name of Dam Beaver Dam Fed ID# NJ 00077 and NJ ID# 503

State Located New Jersey
County Located Cumberland
Coordinates Lat. 3920.2 - Long. 7502.5
Stream Buckshutem Creek
Date of Inspection 10 January 1979

ASSESSMENT OF
GENERAL CONDITIONS


Beaver Dam is assessed to be a fair overall condition and is recommended to be downgraded from a high hazard to a significant hazard category. No detrimental findings were uncovered to render a hazardous assessment. Over-topping of the dam would not greatly increase the danger of loss of life or property damage as the discharge flows directly into the much larger Laurel Lake. Remedial actions recommended to be undertaken under a regular maintenance program in the near future are 1) replace the deteriorated timber in the spillway, 2) rebuild the crest shoulders and remove the trees, 3) remove the trash in the spillway and downstream embankments, and 4) breakup the concrete slope protection and properly rearrange pieces on the backslopes.

The dam has an inadequate spillway capacity, being able to accommodate only 29% of the design flood and it is recommended that further hydraulic/hydrologic studies be undertaken.



F. Keith Jolis P.E.
Project Manager





Spillway

OVERVIEW OF BEAVER DAM

JANUARY 1979

TABLE OF CONTENTS

	<u>Page</u>
Assessment of General Conditions	
Overall View of Dam	
Table of Contents	
Preface	
Section 1 - Project Information	1-5
Section 2 - Engineering Data	6-7
Section 3 - Visual Inspections	8-10
Section 4 - Operational Procedures	11
Section 5 - Hydraulic/Hydrologic	12-13
Section 6 - Structural Stability	14-15
Section 7 - Assessments/Recommendations/ Proposed Remedial Measures	16-17

FIGURES

- Figure 1 - Regional Vicinity Map
- Figure 2 - Plan of Dam
- Figure 3 - Spillway Details

APPENDIX

Check List - Visual Inspection	
Check List - Engineering Data	
Photographs	
Check List - Hydrologic and Hydraulic Data	
Computations	A1-A16

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM
NAME OF DAM: BEAVER DAM FED ID# NJ 00077

SECTION 1 - PROJECT INFORMATION

1.1 GENERAL

a. Authority

This report is authorized by the Dam Inspection Act, Public Law 92-367, and has been prepared in accordance with Contract FPM-36 between Louis Berger & Associates, Inc. and the State of New Jersey and its Department of Environmental Protection, Division of Water Resources. The State, in turn, is under agreement with the U.S. Army Engineer District, Philadelphia, to have this inspection performed.

b. Purpose of Inspection

The purpose of this inspection is to evaluate the structural and hydraulic condition of the Beaver Dam and appurtenant structures, and to determine if the dam constitutes a hazard to human life or property.

1.2 DESCRIPTION OF PROJECT

a. Description of Dam and Appurtenances

Beaver Dam is a relatively old straight earth embankment approximately 700 feet long with a timber box spillway located about 200 feet from the south abutment. The three-sided spillway has a total overall crest length of 43 feet with one section of removeable flashboards 5 feet wide positioned in the center of the upstream face of the inlet. Discharge from the timber box exits downstream through two 66 inch round reinforced concrete pipes. This is the only hydraulic exit within the dam.

b. Location

Beaver Dam is located three-quarters of a mile southwest of the intersection of County Roads 670 (Buckshutem Road) and 627 (Mauricetown Road) in Laurel Lake, Commercial Township, Cumberland County and lies at the upper end of Laurel Lake, about 1.5 miles west of the Maurice River. The Millville Fish and Wildlife Management Area (a State Hunting and Fishing Grounds) is located just to the west of the lake.

c. Size Classification

The maximum hydraulic height of the dam is 10.8 feet and the maximum storage is estimated to be 295 acre-feet. Therefore, the dam is placed in the small size category as defined by the Recommended Guidelines for Safety Inspection of Dams (maximum storage less than 1,000 acre-feet and maximum height less than 25 feet).

d. Hazard Classification

Based on the Corps of Engineers criteria and the fact that in the event of a failure, appreciable damage could be inflicted on the Laurel Lake Dam (located 1.3 miles downstream) and possibly the bridge at Buckshutem Road, the classification is recommended to be downgraded to a significant hazard. Below Beaver Dam, the majority of the homes around Laurel Lake are situated above flood elevation and would probably not be flooded in the event of a failure. Further, the storage capacity of Beaver Lake is relatively small when compared to the size of Laurel Lake. In view of the foregoing, excessive economic loss is not foreseen; hence, the downgraded classification.

e. Ownership

According to Division of Water Resources records the dam is owned by the Laurel Lakes Development Corporation, 1 North 13th Street, Philadelphia, Pa. The inspection team contacted Mr. Harry Smith, Esq., Lake Shore

Drive, Laurel Lake, President of the Laurel Lakes Association who verified that his organization pays for and performs all maintenance.

f. Purpose of Dam

The dam impounds a recreation lake and was constructed by Laurel Lakes Development Corporation when this lake community was initially developed (see next paragraph).

g. Design and Construction History

The dam was reconstructed in 1957 by the Laurel Lake Development Corp. on the site of an older existing earth dam that had failed on November 14, 1927. The initial date of the first instance construction is unknown. This initial failure, which reportedly occurred soon after the dam was built, was believed to be due to an inadequate spillway. A 75 foot gap was washed out in the vicinity of the spillway. Upon reconstruction in 1957, a timber core wall was built across the breached area but the existing sections of embankment were left intact. A new timber box drop inlet was constructed near the location of the earlier spillway and just to the right of the natural channel of Buckshutem Creek. About 6 years ago, the Lake Association added concrete riprap protection on both the upstream and downstream faces of the dam. Barriers have been installed at the abutments to forestall the use of the dam as a roadway. The dam is called Beaver Road Dam locally and at an earlier time, was addressed as the Beach Club Lake Dam.

h. Normal Operating Procedures

There are presently no specific operating procedures at this site except for the periodic maintenance of the spillway structure and embankment by members of the Laurel Lake Community Club. Club members also monitor the dam during periods of heavy flows. The extent and degree to which this takes place is unknown.

1.3 PERTINENT DATA

a. Drainage Area

The drainage area of Beaver Dam is 16.0 square miles.

b. Discharge of Dam Site

The spillway capacity with the reservoir level at the top of dam is calculated to be approximately 800 cfs. No discharge records are available at this site.

c. Elevation (Above M.S.L.)

Top of dam - +21+
Recreation Pool - +16.9 (Spillway crest)
Streambed at Center Line of Dam - +10.2

d. Reservoir

Length of Recreation Pool - 2000 feet
Length of Maximum Pool - 4700 feet

e. Storage

Top of dam - 295 acre-ft.
Recreation pool - 120 acre-ft.

f. Reservoir Surface

Top of dam - 50 acres
Recreation Pool - 30 acres

g. Dam

Type - Earth embankment with timber box spillway

Length - 700 feet

Structural height of spillway works - 25.0 feet

Hydraulic height - 10.8 feet

Freeboard between normal reservoir and top of dam - 4.1 feet

Top width - 10₊ feet

Side slopes - 3H:1V u/s; 2H:1V d/s

Zoning - composition and compactness unknown.
Timber cut-off walls in portions of
dam.

h. Diversion and Regulating Tunnel

None

i. Spillway

Type - 3-sided overflow timber box

Overall length of weir - 43 feet

Effective length - 40 feet

Crest elevation - +16.9 (flashboards in place)

j. Regulating Outlets

Removable flashboards in spillway section.

Minimum invert elevation - +10.7 (flashboards
removed)

SECTION 2 - ENGINEERING DATA

2.1 DESIGN

The only design information located for review were two sheets of the 1957 construction plans for the spillway (attached herein). The work was designed by Mr. John Reutter, N.J.P.E. #3671 and was filed with Dam Application No. 503, dated 27 February 1957. No design computations were available nor were the plans for an earlier dam application (No. 109) located.

2.2 CONSTRUCTION

No information was available.

2.3 OPERATION

Department of Environmental Protection records indicate that the 1957 construction replaced an earlier structure that was washed out. The present dam appears to have operated satisfactorily as designed and reconstructed.

2.4 EVALUATION

a. Availability

In view of the size and hazard classification it is felt that sufficient engineering data is available except for geotechnical data of the embankment.

b. Adequacy

A review of the original plans indicate that the spillway was conservatively designed and from the results of the field inspection, is built in accordance with the design plans. Hence, from a structural standpoint, the engineering data is believed to be adequate.

c. Validity

Based on field observations, the validity of the 1957 design is not challenged but further

investigations would be required to fully assess the permeability of the embankment zones in the areas which were not washed out in the 1927 breaching.

SECTION 3 - VISUAL INSPECTIONS

3.1 a. General

Visual inspections were conducted on January 2 and 11, 1979. The reservoir water level at the time of the latter inspection was about 4 inches above the top of the intake flashboards and was discharging freely although the pool was frozen over. An earlier, informal inspection was conducted in September before the lake was frozen.

b. Dam

The embankment portions were found to be substantially as designed and in a stable condition although the design crest width and side slopes are extremely ill-defined. The lake level appears to be fairly constant during extensive periods as the banks are well stabilized and show little evidence of sloughing at higher water levels. It appears that after the 1927 breaching the uncontrolled flow was allowed to revert into the natural riverbed of Buchshutem Creek (as evidenced by secondary growth in the upper end of the reservoir). The embankment back-slopes are covered with secondary timber growth and there is quite an extensive amount of trash dumped on the downstream face to the right of the spillway. The dam crest is quite uneven and has sloughed off at the shoulder lines. Certain areas near the right abutment have distinct erosion swales established as have numerous other zones on both the upstream and downstream faces. Much of the crest erosion is caused by minibike rutting, especially at the left abutment where the effective crest width is presently only about 5 feet.

Although the difference in normal pool levels between Beaver and Laurel Lakes averages only about 6.5 feet, there is seepage evident along the downstream toes in several zones between 100 and 175 feet north of the spillway channel.

Moreover, a substantial portion of the downstream toe of slope of Beaver Dam is inundated by the Laurel Lake tailwater.

A considerable amount of broken concrete building floor planking has been dumped each side of the 66" RCP pipe outlets. However, it is poorly positioned and its effectiveness as slope protection is thought to be marginal since the planking may be masking eroded pockets or burrows beneath.

c. Appurtenant Structures

The timber box drop inlet and 66-inch reinforced concrete pipe outlets are in satisfactory condition. The exposed concrete headwall at the upstream shoulder line has no major structural cracking and the short 15 foot sections of timber bulkhead on each side of the intake are plumb but have suffered dry-rot in some of the upper planks. The 13 x 17 foot rectangular spillway is founded on eight 12" cedar piles and the outlet pipes are supported by the concrete headwall and cutoff walls. There is a considerable amount of timber debris collected in the box inlet but this can be easily removed. Additionally, there are 3" tongue and groove timber corewalls along the dam axis each side of the spillway and in the zone near the left abutment where the 1927 breaching occurred (see Figure 2).

d. Reservoir

Beaver Lake is substantially clear of debris and has a fairly well defined shoreline composed of the silty and clayey sands which predominate in this area. However, this material is quite susceptible to erosion. Upstream from the lake lies Buckshutem Swamp which has an extensive latent storage capacity. The original subdivision development plans had envisioned a much larger lake (over 200 acres) than the presently impounded reservoir.

e. Downstream Channel

The outlet of the study dam discharges directly into the headwaters of Laurel Lake which is situated directly to the east. This lake is another but much larger community recreational facility and is maintained by an overflow structure just east of the county bridge on Buckshutem Road. This lower dam was rebuilt after having failed in the late 1950's. Immediately below this dam, Buckshutem Creek discharges directly into the tidal flats of the Maurice River.

SECTION 4 - OPERATIONAL PROCEDURES

4.1 PROCEDURES

Operational procedures were not observed by the inspection team. Discussions were held with Mr. Harry Smith, President of the Lake Association and local residents regarding the operational history of the dam.

4.2 MAINTENANCE OF DAM

Maintenance is carried out as part of the dues-paying club membership program for their association's facilities. The dam is periodically inspected and repairs made on an as-needed basis.

4.3 MAINTENANCE OF OPERATING FACILITIES

There are no operating facilities except for the removable stoplogs in the upstream face of the box inlet. It appears these are normally not adjusted as the planking is wedged tightly in place.

4.4 DESCRIPTION OF WARNING SYSTEM IN EFFECT

There is no formalized warning system in effect as the dam has not been overtopped since the early 1927 collapse. Association personnel monitor the spillway during periods of heavy flow to keep it free from debris.

4.5 EVALUATION OF OPERATIONAL ADEQUACY

Present procedures and safeguards are deemed to be adequate in view of the performance record and the lack of hazards at this site. The Laurel Lake Association has an experienced cadre of residents who share a vital interest in the upkeep of their facilities.

SECTION 5 - HYDRAULIC/HYDROLOGIC

5.1 EVALUATION OF FEATURES

a. Design Data

Pursuant to the Recommended Guidelines for Safety Inspection of Dams, Beaver Dam is of small size and significant hazard. Accordingly a spillway design flood of one half the probable maximum flood (PMF) was selected by the inspection team to test the spillway capacity and overtopping potential. Precipitation data was obtained from Hydrometeorological Report No. 33. In accordance with Corps of Engineers directives, the inflow hydrograph and flood routing were obtained utilizing the HEC-1 computer program. Peak inflow to the reservoir for the $\frac{1}{2}$ PMF was 2,760 cfs and remained approximately the same after the inflow was routed through the reservoir. The maximum spillway discharge capacity is calculated to be 800 cfs. Hence, the spillway can accommodate only 29% of the spillway design flood. This flood would cause the dam to be overtopped by approximately 1.1 feet.

b. Experience Data

The dam was originally designed to accommodate a 100-year frequency event of 475 cfs according to Dam Application records. There is no other information available as to the performance of this dam, as there are no streamflow records available.

c. Visual Observations

The dam inlet functions adequately although there was some debris in the inlet at the time of the inspection. Judging from its appearance, the dam's crest has not been overtopped since its 1957 reconstruction. As previously stated, the 1927 failure was attributed to an undersized spillway but no data was available as to its size or discharge capacity.

d. Overtopping Potential

Although the spillway can accommodate less than a third of the design flood, the overtopping potential is believed not to be of a highly critical concern in view of the lake's small storage capacity and low hydraulic head differential.

e. Drawdown Potential

The lake can only be drawn down 6.2 feet to elevation 10.7, (assuming the stop planks can be removed). Drawdown to this elevation would take approximately one day. There is no provision for any further drawdown.

SECTION 6 - STRUCTURAL STABILITY

6.1 EVALUATION OF STRUCTURAL STABILITY

a. Visual Observations

Based on the visual inspection and the review of the spillway design, the Beaver Dam is evaluated as being in a fair overall structural condition. The inspection team was principally concerned with the gradual erosion of the crest embankment shoulders especially to the left of the spillway backslope and below the right abutment. The continual sloughing away of these slopes could eventually create a breaching hazard. Similarly, the trash dumped below the spillway could create a rodent-infestation problem with burrows and their attendant piping weaknesses in the embankment.

The spillway and outfall pipes are in satisfactory condition with minor structural deficiencies. However, the inlet requires periodic cleaning as debris tends to be contained at the pipe entrances.

b. Design & Construction Data

The spillway and outfall foundation supports were deemed to be conservatively designed although no actual computations were available. The hydraulic differential is such that no stress or stability problems are foreseen. There is some concern as to the interface between the 1957 corewall where it joins the earlier installed corewall but this can not be observed without digging test pits. With the modest differential hydraulic head, seepage through the embankment is not viewed as a potentially dangerous condition.

c. Operating Records

Although there are no operating records maintained, there has been little required upkeep of the dam structure.

d. Post Construction Changes

There have been no modifications to the hydraulic capabilities since the installation of the spillway. The broken chunks of concrete building plank that have been dumped on the slopes around the pipe sluiceways and the drop inlet are the only evidences of post-construction changes.

e. Seismic Stability

Beaver Dam is located in Zone 1 and experience indicates that dams will have adequate stability under dynamic loading conditions if stable under static loading conditions.

SECTION 7 - ASSESSMENTS/RECOMMENATIONS/
PROPOSED REMEDIAL MEASURES

7.1 DAM ASSESSMENT

a. Subject to the inherent limitations of the Phase I visual inspection, Beaver Dam is classified as being in a fair overall condition although the spillway is incapable of passing the design flood. The embankment is built of unknown composition but due to its apparent impermeable composition, timber cut-off wall and lack of serious evidence of seepage, is felt to be of a sufficient impervious condition to withstand normal hydraulic heads. The present spillway capacity is inadequate and does not meet the requirements of the Recommended Guidelines for Safety Inspection of Dams, being able to accommodate only 29% of the spillway design flood as calculated by Corps of Engineers criteria. However, the SDF is calculated to overtop the dam by only slightly more than one foot and except for possible erosion damage to the backslopes, the overtopping danger is believed to be negligible.

b. Adequacy of Information

The information obtained for the Phase I inspection is deemed to be adequate and it is believed that little else is available. Performance data is also believed to be non-existent. However, in view of the hazard classification and downstream conditions, the information is considered satisfactory for the assessment contained herein.

c. Urgency

A collapse of Beaver Dam could endanger the lower dam of Laurel Lake but it is felt this event would be highly problematical. In view of all mitigating conditions, no urgency is attached to implementing further studies and it is recommended that the remedial measures

set forth below be taken under advisement in the near future and be undertaken by the owners as part of their regular maintenance program.

d. Necessity for Further Study

Due to the downgraded significant hazard classification recommended herein and the fact that little property damage is likely in the event of a collapse, further structural studies regarding the dam itself are believed to be unnecessary. However, additional hydraulic/hydrologic studies are recommended (in conjunction with the lower dam).


7.2 RECOMMENDATIONS/REMEDIAL MEASURES


a. Recommendations


- 1) On the basis of the present conditions and geometry, remedial improvements to the existing spillway is not warranted. The deteriorated upper members of bulkhead and inlet should be replaced and the debris cleaned out of the inlet and pipes.
- 2) The shoulders of the crest should be regraded, levelled and compacted and the trees removed along the upstream crest.
- 3) The trash should be cleared from the backslope near the south abutment and the area regraded and seeded.
- 4) The randomly dumped concrete building plank could be broken up into smaller segments and seated more uniformly into the backslopes. A gravel bedding layer should be placed under the concrete pieces where complete relocation is feasible.

b. O&M Maintenance and Procedures

No additional procedures other than those presently in effect are warranted except it is recommended that a checklist of periodic maintenance inspections be developed so records of conditions and repairs can be maintained.







<u>Name</u>	<u>Dam</u>	<u>Beaver</u>	<u>County</u>	<u>State</u>	<u>New Jersey</u>	<u>Coordinators</u>	<u>NJDEP</u>
-------------	------------	---------------	---------------	--------------	-------------------	---------------------	--------------

Date(s)	Inspection	2, 11, Jan. 1979	Weather	Cloudy	Temperature	18°

Pool Elevation at Time of Inspection	+ 17.2	M.S.L.	Tailwater at Time of Inspection	+ 11.5	M.S.L.
1	17.2	M.S.L.	11.5	M.S.L.	
2	17.2	M.S.L.	11.5	M.S.L.	
3	17.2	M.S.L.	11.5	M.S.L.	
4	17.2	M.S.L.	11.5	M.S.L.	
5	17.2	M.S.L.	11.5	M.S.L.	
6	17.2	M.S.L.	11.5	M.S.L.	
7	17.2	M.S.L.	11.5	M.S.L.	
8	17.2	M.S.L.	11.5	M.S.L.	
9	17.2	M.S.L.	11.5	M.S.L.	
10	17.2	M.S.L.	11.5	M.S.L.	
11	17.2	M.S.L.	11.5	M.S.L.	
12	17.2	M.S.L.	11.5	M.S.L.	
13	17.2	M.S.L.	11.5	M.S.L.	
14	17.2	M.S.L.	11.5	M.S.L.	
15	17.2	M.S.L.	11.5	M.S.L.	
16	17.2	M.S.L.	11.5	M.S.L.	
17	17.2	M.S.L.	11.5	M.S.L.	
18	17.2	M.S.L.	11.5	M.S.L.	
19	17.2	M.S.L.	11.5	M.S.L.	
20	17.2	M.S.L.	11.5	M.S.L.	
21	17.2	M.S.L.	11.5	M.S.L.	
22	17.2	M.S.L.	11.5	M.S.L.	
23	17.2	M.S.L.	11.5	M.S.L.	
24	17.2	M.S.L.	11.5	M.S.L.	
25	17.2	M.S.L.	11.5	M.S.L.	
26	17.2	M.S.L.	11.5	M.S.L.	
27	17.2	M.S.L.	11.5	M.S.L.	
28	17.2	M.S.L.	11.5	M.S.L.	
29	17.2	M.S.L.	11.5	M.S.L.	
30	17.2	M.S.L.	11.5	M.S.L.	
31	17.2	M.S.L.	11.5	M.S.L.	
32	17.2	M.S.L.	11.5	M.S.L.	
33	17.2	M.S.L.	11.5	M.S.L.	
34	17.2	M.S.L.	11.5	M.S.L.	
35	17.2	M.S.L.	11.5	M.S.L.	
36	17.2	M.S.L.	11.5	M.S.L.	
37	17.2	M.S.L.	11.5	M.S.L.	
38	17.2	M.S.L.	11.5	M.S.L.	
39	17.2	M.S.L.	11.5	M.S.L.	
40	17.2	M.S.L.	11.5	M.S.L.	
41	17.2	M.S.L.	11.5	M.S.L.	
42	17.2	M.S.L.	11.5	M.S.L.	
43	17.2	M.S.L.	11.5	M.S.L.	
44	17.2	M.S.L.	11.5	M.S.L.	
45	17.2	M.S.L.	11.5	M.S.L.	
46	17.2	M.S.L.	11.5	M.S.L.	
47	17.2	M.S.L.	11.5	M.S.L.	
48	17.2	M.S.L.	11.5	M.S.L.	
49	17.2	M.S.L.	11.5	M.S.L.	
50	17.2	M.S.L.	11.5	M.S.L.	
51	17.2	M.S.L.	11.5	M.S.L.	
52	17.2	M.S.L.	11.5	M.S.L.	
53	17.2	M.S.L.	11.5	M.S.L.	
54	17.2	M.S.L.	11.5	M.S.L.	
55	17.2	M.S.L.	11.5	M.S.L.	
56	17.2	M.S.L.	11.5	M.S.L.	
57	17.2	M.S.L.	11.5	M.S.L.	
58	17.2	M.S.L.	11.5	M.S.L.	
59	17.2	M.S.L.	11.5	M.S.L.	
60	17.2	M.S.L.	11.5	M.S.L.	
61	17.2	M.S.L.	11.5	M.S.L.	
62	17.2	M.S.L.	11.5	M.S.L.	
63	17.2	M.S.L.	11.5	M.S.L.	
64	17.2	M.S.L.	11.5	M.S.L.	
65	17.2	M.S.L.	11.5	M.S.L.	
66	17.2	M.S.L.	11.5	M.S.L.	
67	17.2	M.S.L.	11.5	M.S.L.	
68	17.2	M.S.L.	11.5	M.S.L.	
69	17.2	M.S.L.	11.5	M.S.L.	
70	17.2	M.S.L.	11.5	M.S.L.	
71	17.2	M.S.L.	11.5	M.S.L.	
72	17.2	M.S.L.	11.5	M.S.L	

Inspection Personnel:

K. Jolls	L. Cranston
R. Lang	
E. Simone	

K. Jolls

CONCRETE/MASONRY DAMS

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SEE PAGE ON LEAKAGE		
STRUCTURE TO ABUTMENT/EMBANKMENT JUNCTIONS	N/A	Pipes buried through dam embankment.
DRAINS	None	
WATER PASSAGES	None	
FOUNDATION	Timber sheeting and piles in spillway.	

CONCRETE/MASONRY DAMS

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS CONCRETE SURFACES	N/A	Entire structural system exposed is timber except upstream concrete headwall.
STRUCTURAL CRACKING	N/A	
VERTICAL AND HORIZONTAL ALIGNMENT	Satisfactory but irregular.	Short concrete parapet wall at spillway headwall.
MONOLITH JOINTS	N/A	
INSTRUCTION JOINTS	N/A	

EMBANKMENT

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS	Some observed running transversely down slopes.	Sand and gravel fill repairs (little clay binder).
UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE	None	The downstream toe completely obscured by siltation and tail-water from Laurel Lake.
SLOUGHING OR EROSION OF EMBANKMENT AND ABUTMENT SLOPES	Headwaters of Laurel Lake cover downstream toe of slope.	Downstream slope on left-garbage disposal area.
VERTICAL AND HORIZONTAL ALIGNMENT OF THE CREST	Quite uneven. Evidence of recent repairs.	Very poorly maintained.
CURB FAILURES	Loose pieces of flexicore concrete plank forms protection around spillway and adjacent slopes.	Poorly placed. Affords very little protection. Requires seating and proper positioning.

EMBANKMENT

REMARKS OR RECOMMENDATIONS

OBSERVATIONS

QUAL EXAMINATION OF

FUNCTION OF EMBANKMENT
AND ABUTMENT, SPILLWAY
AND DAM

Satisfactory

ANY NOTICEABLE SEEPAGE

Minor - to left of spillway
(100 to 175')

Seepage observed only at toe of
slope and not up within embankment
area.

STAFF GAGE AND RECORDER

None

AINS

None

OUTLET WORKS

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CRACKING AND SPALLING OF CONCRETE SURFACES IN OUTLET CONDUIT	No concrete except pipe headwalls (all underwater):	
INTAKE STRUCTURE	17 x 13 x 6' drop timber drop inlet with concrete headwall at dam crest. (16' long).	Vertical timber planking driven along concrete headwall each side.
OUTLET STRUCTURE	2-66" RCP.	Pipes in good alinement. Exhibit no settling.
OUTLET CHANNEL	Some scour just below outlet of pipes. Short channel length before discharging into Laurel Lake.	Ill-defined channel.
EMERGENCY GATE	None except removable stop logs in front of box inlet.	

UNGATED SPILLWAY

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE WEIR	N/A	
APPROACH CHANNEL	N/A	
DISCHARGE CHANNEL	N/A	
BRIDGE AND PIERS	None	

GATED SPILLWAY

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE SILL	N/A	
APPROACH CHANNEL	N/A	
DISCHARGE CHANNEL	N/A	
BRIDGE AND PIERS	N/A	
GATES AND OPERATION EQUIPMENT	N/A	

INSTRUMENTATION

VISUAL EXAMINATION MONUMENTATION/SURVEYS	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
	None observed at dam axis.	Riparian Monument No. 2009 at left abutment. (Could not be located in field).
OBSERVATION WELLS	None	
WEIRS	None	
PIEZOMETERS	None	
OTHER		



RESERVOIR

VISUAL EXAMINATION OF

OBSERVATIONS

REMARKS OR RECOMMENDATIONS

SLOPES

Very flat. Many dead trees in water.

Numerous dead trees in pool in upstream end of lake.

SEDIMENTATION

Silted right up to spillway crest at dam.

Entire lake appears to be quite shallow.

DOWNSTREAM CHANNEL

REMARKS OR RECOMMENDATIONS

OBSERVATIONS

VISUAL EXAMINATION OF

CONDITION

(OBSTRUCTIONS,
DEBRIS, ETC.)

Much debris and sewage foam at
outlet.

SLOPES

Flat

APPROXIMATE NO.
OF HOMES AND
POPULATION

None within potential
flooding zones.

Homes along Laurel Lake sufficiently
above flood elevations.

CHECK LIST
ENGINEERING DATA
DESIGN, CONSTRUCTION, OPERATION

ITEM	REMARKS
PLAN OF DAM	Available * * N. J. D. E. P.
REGIONAL VICINITY MAP	Available (Quad sheet)
CONSTRUCTION HISTORY	Available *
TYPICAL SECTIONS OF DAM	Available *
HYDROLOGIC/HYDRAULIC DATA	Available *
OUTLETS - PLAN	Available *
- DETAILS	
- CONSTRAINTS	
- DISCHARGE RATINGS	
RAINFALL/RESERVOIR RECORDS	None

ITEM	REMARKS
DESIGN REPORTS	Not available
GEOLOGY REPORTS	Not available
DESIGN COMPUTATIONS HYDROLOGY & HYDRAULICS DAM STABILITY SEEPAGE STUDIES	Not available
MATERIALS INVESTIGATIONS BORING RECORDS LABORATORY FIELD	Only 1 boring on plans.
POST-CONSTRUCTION SURVEYS OF DAM	N/A
BORROW SOURCES.	N/A

ITEM REMARKS

MONITORING SYSTEMS

None

MODIFICATIONS

None

HIGH POOL RECORDS

None

POST CONSTRUCTION ENGINEERING
STUDIES AND REPORTS

None

PRIOR ACCIDENTS OR FAILURE OF DAM
DESCRIPTION
REPORTS

Available

MAINTENANCE
OPERATION
RECORDS

N/A

ITEM	REMARKS
SPILLWAY PLAN	Available*
SECTIONS	Available*
DETAILS	Available*
OPERATING EQUIPMENT PLANS & DETAILS	None




Timber box spillway

September 1978



Outfall of 2-66" \emptyset R.C.P.

September 1978



View North along crest

September 1978



Downstream channel (Laurel Lake)

September 1978



Earth embankment left of spillway

January 1979



View South from left abutment

January 1979

CHECK LIST
HYDROLOGIC AND HYDRAULIC DATA
ENGINEERING DATADRAINAGE AREA CHARACTERISTICS: 16.0 sq.mi. (flat N.J. sand shrub pinelands)ELEVATION TOP NORMAL POOL (STORAGE CAPACITY): + 16.90 (120 acre-feet)ELEVATION TOP FLOOD CONTROL POOL (STORAGE CAPACITY): + 21.0 (295 acre-feet)ELEVATION MAXIMUM DESIGN POOL: + 19.5 (Application No. 503)ELEVATION TOP DAM: + 21.0 M.S.L.

CREST:

a. Elevation + 19.5b. Type 3 sided timber box drop inletc. Width 1.0'd. Length 40'e. Location Spillover Nonef. Number and Type of Gates None

OUTLET WORKS:

a. Type 2-66" RCPb. Location 200 ± feet from south abutmentc. Entrance inverts + 10.2d. Exit inverts + 10.2e. Emergency draindown facilities None except stoplog removalHYDROMETEOROLOGICAL GAGES: Partial record station at Laurel Lakea. Type -b. Location Rt. 555 bridge at lower end of Laurel Lake.c. Records 1976 only. 1.1 CFS maximum flowMAXIMUM NON-DAMAGING DISCHARGE: 1100 CFS (928 CFS on Application No. 503)

BY D DATE Jan 77
CHKD. BY _____ DATE _____
SUBJECT _____

LOUIS BERGER & ASSOCIATES INC.

SHEET NO. 11 OF _____
PROJECT C-226

Snyder Coefficient (From Corps of Eng. Atlas)

$$C_p = 0.43$$

Length of longest watercourse $L \approx 5.61$ miles

Length along watercourse to centroid $L_c = 3.03$ miles

$$L \times L_c = 17.0$$

Using plate 17, curve #2 Special project memo no. 452

$$t_p = 18 \text{ hours}$$


Precipitation

PMF for 200 sq. mi. and 24 hr duration = 24"

Maximum 6-hour percentage = 110

Maximum 12-hour percentage = 119

Maximum 24-hour percentage = 128



BY D. J. M. DATE 3-79

LOUIS BERGER & ASSOCIATES INC.


SHEET NO. 43 OF 43CHKD. BY DATE BEAVER LAKE DAM IMPROVEMENTPROJECT SUBJECT Spillway discharge calculations

Effective length of crest = 40' invert of pipe = 51.100 (@ outlet)

Over Crest			Thru 2 60" pipe			Controlling discharge		
<u>H</u>	<u>C</u>	<u>Q</u>	<u>H</u>	<u>C</u>	<u>Q</u>	<u>H</u>	<u>C</u>	<u>Q</u>
1	3.1	124	7.9	589				124
2	3.1	351	8.9	625				351
3	3.1	644	9.9	659				644
4	3.1	992	10.9	692				692
5	3.1	1386	11.9	723				723
5.5	3.1	1599	12.4	738				738
6	3.1	1822	12.9	753				753
6.5	3.1	2055	13.4	767				767
7	3.1	2297	13.9	781				781

Over dam L=680'			<u>Σ Q</u>	
<u>H</u>	<u>C</u>	<u>Q</u>	<u>H</u>	<u>Q</u>
			1	124
			2	351
			3	644
			4	692
0.9	2.6	1,510	5	2,233
1.4	2.6	2,929	5.5	3,667
1.9	2.6	4,630	6.0	5,383
2.4	2.6	6,574	6.5	7,341
2.9	2.6	8,731	7.0	9,512

BEAVER LAKE DAM STAGE DISCHARGE CURVE




BY D.L. DATE Jan '71
 CHKD. BY _____ DATE _____
 SUBJECT _____

LOUIS BERGER & ASSOCIATES INC.

BEAVER LAKE DAM INSPECTION
STAGE-STORAGE CALCULATION

SHEET NO. 15 OF _____
 PROJECT C-226

Area of lake at elev 16.90 = 30 acres
 Area of contour at elev. 20.0 = 49.4 acres




$$\text{Increment in volume} = \Delta V \approx (x + \Delta x)y$$

Height above crest (ft)	Storage (acre-ft.)
1	33
2	73
3	118
4	170
5	228
6	293
7	363
8	440
9	523
10	613

BY D.L. DATE Jan 79 SUBJECT SEASER DAM
CHKD. BY _____ DATE _____ STAGE - STORAGE

SHEET NO. 16 OF _____
JOB NO. C-226



BY D.L. DATE Jan 71

LOUIS BERGER & ASSOCIATES INC.

SHEET NO. 17 OF

CHKD. BY DATE

FLINER LAKE DAM TOWNSHIP

PROJECT C-226

SUBJECT

DRAWDOWN CAPACITY

Drawdown possible with stopplanks removed

Minimum invert elevation = 10.7'

Effective width = 5.0'

$$\begin{aligned}\text{Volume of lake} &= 30 \times 43560 \times 4.0 \\ &= 5,227,200 \text{ ft}^3\end{aligned}$$

Assume drawdown under average head of 3.10'

$C = 3.10$

$$\begin{aligned}\text{Discharge} &= 3.10 \times 5.0 \times (3.10)^{1.5} \\ &= 85 \text{ cfs}\end{aligned}$$

Time required to drawdown lake to El. 10.70

$$= \frac{5,227,200}{85 \times 3600}$$

$$= 17.1 \text{ hours} \quad \approx 0.70 \text{ days say one day.}$$

BY D J M DATE 4-79
CHKD. BY _____ DATE _____
SUBJECT _____

LOUIS BERGER & ASSOCIATES INC.

REARER LAKE DAM

SHEET NO. A2 OF _____
PROJECT _____

REARER LAKE DAM INSPECTION SOUTH GROUP C226

BY R.G.LANG
JANUARY 1979

JOB SPECIFICATION
NQ NHR NMIN IDAY IHR IMIN METRC IPLT IPRT NSTAN
150 2 0 0 0 0 0 0 0
JOPER 5 NWT 0

MULTI-PLAN ANALYSES TO BE PERFORMED
NPLAN= 1 NRTIO= 5 LRTIO= 1
RTIOS= 1.00 0.50 0.40 0.20 0.10

SUB-AREA RUNOFF COMPUTATION

INFLOW HYDROGRAPH
ISTAQ 3

ICOMP IECON ITAPE JPLT JPRY INAME
0 0 0 0 0 1

HYDROGRAPH DATA
IHYDG IUHG TAREA SNAP TRSDA TRSPC RATIO ISNOW ISAME LOCAL
1 1 16.00 0.0 16.00 0.0 0.0 0 1 0

PRECIP DATA
SPFE PMS R6 R12 R24 R48 R72 R96
0.0 24.00 110.00 119.00 128.00 0.0 0.0 0.0

TRSPC COMPUTED BY THE PROGRAM IS 0.816

LOSS DATA
STRKR DLTKR RTIOL ERAIN STRKS RTIOK STRIL CNSTL ALSMX RTIMP
0.0 0.0 1.00 0.0 0.0 1.00 0.50 0.10 0.0 0.0

UNIT HYDROGRAPH DATA
TP= 18.00 CP=0.43 NTA= 0

RECESSION DATA
STRTO= 0.0 ORCSN= 0.0 RTIOR= 1.00
APPROXIMATE CLARK COEFFICIENTS FROM GIVEN SNYDER CP AND TP ARE TC= 9.38 AND R=15.27 INTERVALS

UNIT HYDROGRAPH 86 END-OF-PERIOD ORIGINATES, LAG= 18.10 HOURS, CP= 0.43 VOL= 1.00
8. 30. 62. 100. 142. 182. 214. 238. 250. 248.
234. 219. 205. 192. 180. 168. 158. 148. 138. 130.
121. 114. 106. 100. 93. 87. 82. 77. 72. 67.
63. 59. 55. 52. 49. 45. 43. 40. 37. 35.
33. 29. 27. 25. 24. 22. 21. 19. 18. 18.
17. 16. 15. 14. 13. 12. 11. 11. 10. 9.
9. 8. 7. 6. 6. 6. 6. 5. 5. 5.
5. 4. 4. 4. 4. 3. 3. 3. 3. 3.

BY D J M DATE 4-79

CHKD. BY _____ DATE _____

SUBJECT _____

LOUIS BERGER & ASSOCIATES INC.

BEAVER LAKE DAMSHEET NO. A9 OF _____

PROJECT _____

END-OF-PERIOD FLOW			
TIME	RAIN	EXCS	COMP Q
1	0.23	0.00	0.
2	0.23	0.00	0.
3	0.23	0.03	0.
4	0.59	0.39	4.
5	0.59	0.39	17.
6	0.59	0.39	42.
7	5.60	5.40	122.
8	11.42	11.22	377.
9	4.52	4.32	882.
10	0.35	0.15	1586.
11	0.35	0.15	2414.
12	0.35	0.15	3296.
13	0.0	0.0	4130.
14	0.0	0.0	4812.
15	0.0	0.0	5290.
16	0.0	0.0	5517.
17	0.0	0.0	5463.
18	0.0	0.0	5211.
19	0.0	0.0	4900.
20	0.0	0.0	4596.
21	0.0	0.0	4307.
22	0.0	0.0	4034.
23	0.0	0.0	3778.
24	0.0	0.0	3539.
25	0.0	0.0	3314.
26	0.0	0.0	3104.
27	0.0	0.0	2907.
28	0.0	0.0	2723.
29	0.0	0.0	2550.
30	0.0	0.0	2388.
31	0.0	0.0	2237.
32	0.0	0.0	2095.
33	0.0	0.0	1962.
34	0.0	0.0	1838.
35	0.0	0.0	1721.
36	0.0	0.0	1612.
37	0.0	0.0	1510.
38	0.0	0.0	1414.
39	0.0	0.0	1324.
40	0.0	0.0	1240.
41	0.0	0.0	1162.
42	0.0	0.0	1088.
43	0.0	0.0	1019.
44	0.0	0.0	954.
45	0.0	0.0	894.
46	0.0	0.0	837.
47	0.0	0.0	784.
48	0.0	0.0	734.
49	0.0	0.0	688.
50	0.0	0.0	644.
51	0.0	0.0	603.
52	0.0	0.0	565.
53	0.0	0.0	529.
54	0.0	0.0	496.
55	0.0	0.0	464.
56	0.0	0.0	435.
57	0.0	0.0	407.
58	0.0	0.0	381.

BY D.J.M. DATE 4-79
CHKD. BY _____ DATE _____
SUBJECT _____

LOUIS BERGER & ASSOCIATES INC.

BEAVER LAKE DAM

SHEET NO. 110 OF _____
PROJECT _____

59	0.0	0.0	357.
60	0.0	0.0	334.
61	0.0	0.0	313.
62	0.0	0.0	293.
63	0.0	0.0	275.
64	0.0	0.0	257.
65	0.0	0.0	241.
66	0.0	0.0	226.
67	0.0	0.0	211.
68	0.0	0.0	198.
69	0.0	0.0	185.
70	0.0	0.0	174.
71	0.0	0.0	163.
72	0.0	0.0	152.
73	0.0	0.0	143.
74	0.0	0.0	134.
75	0.0	0.0	125.
76	0.0	0.0	117.
77	0.0	0.0	110.
78	0.0	0.0	103.
79	0.0	0.0	96.
80	0.0	0.0	90.
81	0.0	0.0	84.
82	0.0	0.0	79.
83	0.0	0.0	74.
84	0.0	0.0	69.
85	0.0	0.0	65.
86	0.0	0.0	61.
87	0.0	0.0	57.
88	0.0	0.0	53.
89	0.0	0.0	50.
90	0.0	0.0	46.
91	0.0	0.0	43.
92	0.0	0.0	39.
93	0.0	0.0	28.
94	0.0	0.0	8.
95	0.0	0.0	1.
96	0.0	0.0	1.
97	0.0	0.0	0.
98	0.0	0.0	0.
99	0.0	0.0	0.
100	0.0	0.0	0.
101	0.0	0.0	0.
102	0.0	0.0	0.
103	0.0	0.0	0.
104	0.0	0.0	0.
105	0.0	0.0	0.
106	0.0	0.0	0.
107	0.0	0.0	0.
108	0.0	0.0	0.
109	0.0	0.0	0.
110	0.0	0.0	0.
111	0.0	0.0	0.
112	0.0	0.0	0.
113	0.0	0.0	0.
114	0.0	0.0	0.
115	0.0	0.0	0.
116	0.0	0.0	0.
117	0.0	0.0	0.
118	0.0	0.0	0.
119	0.0	0.0	0.

BY D.L.M. DATE 4-79
CHKD. BY _____ DATE _____
SUBJECT _____

LOUIS BERGER & ASSOCIATES INC.

BEAVER LAKE DAM

SHEET NO. A 11 OF _____
PROJECT _____

120	0.0	0.0	0.
121	0.0	0.0	0.
122	0.0	0.0	0.
123	0.0	0.0	0.
124	0.0	0.0	0.
125	0.0	0.0	0.
126	0.0	0.0	0.
127	0.0	0.0	0.
128	0.0	0.0	0.
129	0.0	0.0	0.
130	0.0	0.0	0.
131	0.0	0.0	0.
132	0.0	0.0	0.
133	0.0	0.0	0.
134	0.0	0.0	0.
135	0.0	0.0	0.
136	0.0	0.0	0.
137	0.0	0.0	0.
138	0.0	0.0	0.
139	0.0	0.0	0.
140	0.0	0.0	0.
141	0.0	0.0	0.
142	0.0	0.0	0.
143	0.0	0.0	0.
144	0.0	0.0	0.
145	0.0	0.0	0.
146	0.0	0.0	0.
147	0.0	0.0	0.
148	0.0	0.0	0.
149	0.0	0.0	0.
150	0.0	0.0	0.

SUM 25.05 22.59 115995.

	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CFS	5517.	5424.	4631.	2831.	115997.
INCHES		3.15	10.77	19.75	22.48
AC-FT		2691.	9191.	16856.	19183.

HYDROGRAPH AT STA 3 FOR PLAN 1, RTIO 1

0.	0.	0.	4.	17.	42.	122.	377.	882.	1586.
2414.	3296.	4130.	4812.	5290.	5517.	5463.	5211.	4900.	4596.
4307.	4034.	3778.	3539.	3314.	3104.	2907.	2723.	2550.	2388.
2237.	2095.	1962.	1838.	1721.	1612.	1510.	1414.	1324.	1240.
1162.	1088.	1019.	954.	894.	837.	784.	734.	688.	644.
603.	565.	529.	496.	464.	435.	407.	381.	357.	334.
313.	293.	275.	257.	241.	226.	211.	198.	185.	174.
163.	152.	143.	134.	125.	117.	110.	103.	96.	90.
84.	79.	74.	69.	65.	61.	57.	53.	50.	46.
43.	39.	28.	8.	1.	1.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.

	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CFS	5517.	5424.	4631.	2831.	115997.
INCHES		3.15	10.77	19.75	22.48
AC-FT		2691.	9191.	16856.	19183.

SUBJECT_____

BEAVER LAKE DAM

PROJECT _____

[illegible]

BY D J M DATE 4-79
CHKD. BY _____ DATE _____
SUBJECT _____

LOUIS BERGER & ASSOCIATES INC.

BEAVER LAKE DAM

SHEET NO. 114 OF _____
PROJECT _____

0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	STOR	4.	13.	38.	91.	179.
231.	247.	269.	281.	1.	295.	295.	290.	285.	279.
274.	268.	264.	259.	253.	248.	243.	239.	234.	230.
227.	222.	217.	213.	208.	204.	201.	197.	194.	191.
188.	185.	182.	180.	178.	176.	174.	172.	170.	166.
156.	141.	123.	107.	97.	91.	86.	82.	78.	74.
70.	67.	63.	60.	57.	54.	51.	49.	46.	44.
42.	40.	38.	36.	35.	33.	32.	30.	28.	27.
25.	24.	22.	21.	19.	18.	17.	16.	15.	14.
13.	12.	11.	8.	5.	3.	1.	1.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.

	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CFS	5495.	5414.	4636.	2823.	115997.
INCHES		3.15	10.78	19.69	22.48
AC-FT		2686.	9199.	16805.	19183.

0.	0.	0.	0.	STATION	33.	PLAN 1,	RTIO 2	72.	209.	481.
685.	1651.	1937.	2365.	1.	3.	8.	24.	72.	2473.	2320.
2180.	2048.	1916.	1795.	2613.	2750.	2742.	2628.	2473.	2320.	2320.
1135.	1063.	995.	932.	873.	818.	766.	717.	690.	683.	683.
671.	656.	612.	529.	482.	448.	418.	391.	366.	344.	344.
323.	303.	284.	266.	249.	234.	219.	205.	192.	180.	180.
168.	158.	148.	138.	130.	122.	116.	110.	103.	97.	97.
91.	85.	80.	75.	70.	66.	61.	57.	54.	50.	50.
47.	44.	41.	39.	36.	34.	32.	30.	28.	26.	26.
24.	22.	20.	15.	9.	5.	3.	1.	1.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.

0.	0.	0.	0.	STOR	2.	6.	19.	48.	93.
162.	205.	215.	229.	1.	235.	239.	238.	236.	228.
224.	219.	214.	210.	206.	202.	198.	195.	192.	189.
186.	183.	181.	179.	177.	175.	173.	171.	168.	160.
148.	131.	113.	100.	93.	88.	83.	79.	75.	72.
68.	65.	61.	58.	55.	52.	50.	47.	45.	43.
41.	39.	37.	36.	34.	32.	31.	29.	27.	26.
24.	23.	21.	20.	19.	17.	16.	15.	14.	13.
13.	12.	11.	10.	10.	9.	8.	8.	7.	7.
6.	6.	5.	4.	2.	1.	1.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.

	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CFS	2750.	2707.	2314.	1412.	58000.
INCHES		1.57	5.38	9.85	11.24

BY D.J.M. DATE 4-79

LOUIS BERGER & ASSOCIATES INC.

SHEET NO. A15 OF

CHKD. BY _____ DATE _____

BEAVER LAKE DAM

PROJECT _____

SUBJECT _____

AC-FT			1343.	4592.	8405.	9592.			
			STATION 33, PLAN 1, RTIO 3						
0.	0.	0.	0.	2.	7.	19.	57.	158.	374.
650.	961.	1689.	1827.	2096.	2187.	2200.	2110.	1988.	1865.
1748.	1637.	1533.	1436.	1345.	1260.	1180.	1105.	1035.	969.
908.	850.	796.	746.	698.	688.	679.	666.	649.	573.
508.	467.	435.	407.	381.	357.	335.	315.	296.	277.
259.	243.	228.	213.	200.	187.	175.	164.	154.	144.
135.	126.	120.	113.	107.	100.	94.	88.	83.	78.
73.	68.	64.	60.	56.	52.	49.	46.	43.	40.
38.	35.	33.	31.	29.	27.	25.	24.	22.	21.
19.	18.	16.	12.	7.	4.	2.	1.	1.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.

			STOR						
0.	0.	0.	0.	1.	2.	5.	15.	39.	77.
124.	180.	206.	211.	221.	224.	225.	222.	217.	213.
208.	204.	201.	197.	194.	191.	188.	185.	182.	180.
178.	176.	174.	172.	170.	166.	156.	142.	123.	107.
97.	91.	86.	82.	78.	74.	70.	67.	63.	60.
57.	54.	51.	49.	46.	44.	42.	40.	38.	36.
35.	33.	32.	30.	28.	27.	25.	24.	22.	21.
19.	18.	17.	16.	15.	14.	13.	12.	11.	11.
10.	9.	9.	8.	8.	7.	7.	6.	6.	6.
5.	5.	4.	3.	2.	1.	1.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.

	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CFS	2200.	2165.	1860.	1129.	46400.
INCHES		1.26	4.32	7.88	8.99
AC-FT		1074.	3690.	6722.	7673.

			STATION 33, PLAN 1, RTIO 4						
0.	0.	0.	0.	1.	3.	10.	29.	75.	167.
316.	491.	649.	683.	1062.	1088.	1102.	1054.	994.	932.
874.	819.	767.	718.	690.	683.	672.	656.	614.	530.
483.	448.	418.	392.	367.	344.	324.	304.	285.	267.
250.	234.	219.	205.	192.	180.	169.	158.	148.	138.
130.	122.	116.	110.	103.	97.	91.	85.	80.	75.
70.	66.	61.	58.	54.	50.	47.	44.	41.	39.
36.	34.	32.	30.	28.	26.	25.	23.	22.	20.
19.	18.	17.	16.	15.	14.	13.	12.	11.	10.
10.	9.	8.	6.	4.	2.	1.	1.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.

			STOR						
0.	0.	0.	0.	0.	1.	3.	8.	20.	41.
67.	95.	123.	161.	183.	184.	185.	183.	181.	179.

BY D.J.M. DATE 4-79
 CHKD. BY _____ DATE _____
 SUBJECT _____

LOUIS BERGER & ASSOCIATES INC.

SHEET NO. A16 OF _____
 PROJECT _____

177.	175.	173.	171.	168.	160.	148.	131.	113.	100.
93.	88.	83.	79.	75.	72.	68.	65.	61.	58.
55.	52.	50.	47.	45.	43.	41.	39.	37.	36.
34.	33.	31.	29.	27.	26.	24.	23.	21.	20.
19.	17.	16.	15.	14.	13.	13.	12.	11.	10.
10.	9.	8.	8.	7.	7.	7.	6.	6.	5.
5.	5.	4.	4.	4.	4.	3.	3.	3.	3.
3.	2.	2.	2.	1.	1.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.

	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CFS	1102.	1084.	899.	564.	23200.
INCHES		0.63	2.09	3.93	4.50
AC-FT		538.	1783.	3358.	3837.

STATION 33, PLAN 1, RTIO 5									
0.	0.	0.	0.	1.	2.	5.	14.	37.	78.
140.	233.	321.	406.	475.	521.	541.	536.	515.	487.
458.	429.	402.	377.	353.	332.	312.	293.	274.	257.
240.	225.	211.	198.	185.	173.	162.	152.	142.	133.
125.	119.	112.	106.	100.	93.	88.	82.	77.	72.
67.	63.	59.	55.	52.	49.	46.	43.	40.	37.
35.	33.	31.	29.	27.	25.	24.	22.	21.	19.
18.	17.	16.	15.	14.	13.	12.	11.	11.	10.
9.	9.	8.	8.	7.	7.	6.	6.	6.	5.
5.	4.	4.	3.	2.	1.	1.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.

STOR									
0.	0.	0.	0.	0.	0.	1.	4.	10.	21.
36.	52.	68.	82.	92.	99.	102.	101.	98.	94.
89.	85.	81.	77.	73.	70.	66.	63.	59.	56.
54.	51.	48.	46.	44.	42.	40.	38.	36.	35.
33.	32.	30.	28.	26.	25.	23.	22.	20.	19.
18.	17.	16.	15.	14.	13.	12.	11.	11.	10.
9.	9.	8.	8.	7.	7.	6.	6.	6.	5.
5.	5.	4.	4.	4.	3.	3.	3.	3.	3.
3.	2.	2.	2.	2.	2.	2.	2.	1.	1.
1.	1.	1.	1.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.

	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CFS	541.	532.	458.	282.	11600.
INCHES		0.31	1.07	1.96	2.25
AC-FT		264.	909.	1677.	1918.

PEAK FLOW SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS

OPERATION	STATION	PLAN	RATIOS APPLIED TO FLOWS				
			1.00	0.50	0.40	0.20	0.10
HYDROGRAPH AT	3	1	5517.	2759.	2207.	1103.	552.
		2	927.	0.	0.	0.	0.
ROUTED TO	33	1	5495.	2750.	2200.	1102.	541.
		2	927.	0.	0.	0.	0.